

- Thermopile IR-Sensor
- Filter for NDIR CO2 Gas Detection
- Single Element
- Very High Signal
- Flat Filter
- Small Package
- Accurate Reference Sensor

DESCRIPTION

Thermopiles are mainly used for contactless temperature or non-dispersive infrared measurement in many applications. Their function is to transfer the heat radiation emitted from the objects or other infrared sources into a voltage output.

•

FEATURES

APPLICATIONS

NDIR CO₂ Gas Detection

- Very High Signal
- Accurate Reference Sensor
- 4.26µm Narrow Band Pass
- Small TO-18 package

ABSOLUTE MAXIMUM RATINGS

Parameter	Symbol	Min	Typical	Max	Unit	Description
Storage Temperature	Ts	-20	+20	+85	°C	permanent
Storage Temperature	Ts	-20	+20	+100	°C	non permanent




PERFORMANCE SPECS

Parameter	Symbol	Value	Unit	Condition
Operating Ambient Temperature	T _{Amb}	-20 to +85	°C	permanent
Operating Ambient Temperature	T _{Amb}	-20 to +100	°C	non permanent
Package		TO-18		
Absorber Area	A	1.4 × 1.4	mm ²	
Thermopile Resistance	R _{TP}	180 ± 60	kΩ	T _{Amb} = +25 ℃
Temperature Coefficient of Thermopile Resistance	TCR _{TP}	-0.06 ± 0.04	%/K	$T_{Amb} = +25 \circ C \text{ to } +75 \circ C$
Voltage Response	V _{TP}	depends on light source	mV	
Temperature Coefficient of Voltage Response	TCV _{TP}	-0.45 ± 0.08	%/K	$T_{Amb} = +25 \circ C \text{ to } +75 \circ C$
Noise Equivalent Voltage	NEV	130	nV/Hz ^½	T _{Amb} = +25 ℃
Rise Time	τ_{63}	22 ± 5	ms	
Ambient Temperature Sensor		Ni-RTD		
Ambient Temperature Sensor Resistance	R _{Ni-RTD}	1000 ± 4	Ω	T _{Amb} = 0 ℃
Temperature Coefficient of Ni-RTD	TC _{Ni-RTD}	6178 ±150	ppm/K	$T_{Amb} = 0 \degree C$ to $+100 \degree C$



OPTICAL CHARACTERISTICS





FILTER CHARACTERISTICS






Figure 3: Filter transmission curve



ELECTRICAL CONNECTIONS

Pin	Symbol	
1	TP +	
2	Ni-RTD	
3	TP -	
4	GND	




Figure 4: Electrical connections - bottom view of thermopile

MECHANICAL DIMENSIONS




Figure 5: Mechanical dimensions of thermopile



ORDERING INFORMATION

Part DescriptonTS418-1N426Part No.G-TPCO-035

TECHNICAL CONTACT INFORMATION

NORTH AMERICA	EUROPE	ASIA		
Measurement Specialties, Inc. 910 Turnpike Road Shrewsbury, MA 01545 United States Phone: +1-508-842-0516 Fax: +1-508-842-0342 Email: temperature.sales.amer@meas- <u>spec.com</u> Web: <u>www.meas-spec.com</u>	MEAS Deutschland GmbH Hauert 13 D-44227 Dortmund Germany Phone: +49-(0)231-9740-0 Fax: +49-(0)231-9740-20 Email: <u>info.de@meas-spec.com</u> Web: <u>www.meas-spec.com</u>	Measurement Specialties China Ltd. No. 26, Langshan Road High-tech Park (North) Nanshan District, Shenzhen 518057 China Phone: +86-755-33305088 Fax: +86-755-33305099 Email: temperature.sales.asia@meas- <u>Spec.com</u> Web: <u>www.meas-spec.com</u>		

The information in this sheet has been carefully reviewed and is believed to be accurate; however, no responsibility is assumed for inaccuracies. Furthermore, this information does not convey to the purchaser of such devices any license under the patent rights to the manufacturer. Measurement Specialties, Inc. reserves the right to make changes without further notice to any product herein. Measurement Specialties, Inc. makes no warranty, representation or guarantee regarding the suitability of its product for any particular purpose, nor does Measurement Specialties, Inc. assume any liability arising out of the application or use of any product or circuit and specifically disclaims any and all liability, including without limitation consequential or incidental damages. Typical parameters can and do vary in different applications. All operating parameters must be validated for each customer application by customer's technical experts. Measurement Specialties, Inc. does not convey any license under its patent rights nor the rights of others.